

Attorney Questionnaire

Inspector: Kevin Vann

File #: CE2021-0002 OR 1688 PG 229 Zoning: RR

Are you a qualified Inspector for Sumter County? Yes No

Do you maintain a written record of this case? Yes No

May we enter that record into evidence at this time and mark it as such? Yes No

May we return the record to the inspector at this time for use in the hearing process? Yes No

Are you familiar with property owned by: Property Owner Name: FLINCHUM, BEVERLY R
Tenant Name: _____

Was a Notice of Hearing sent for today? Yes No How? Certified Mail? Yes No
Posting? Yes No 4/16/21

What is the General Location of this property? croom Parcel #: R14B024

What is the Property Address? 4817 CR 686, Webster, FL 33597

When did this case begin? 1/8/21

Have you had any occasion to visit the property? Yes No

Did you view any Code violations? Yes No

What were those violations and can you explain them?

CE2021-0002

2009 I.P.M.C.

108.1.1 Unsafe structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.

(1/11/2021 2:55 PM KV)

Property was posted as UNSAFE

CE2021-0002

2009 I.P.M.C.

108.1.3 Structure unfit for human occupancy.

A structure is unfit for human occupancy whenever the code official finds that such structure is unsafe, unlawful or because of the degree to which the structure is in disrepair or lacks maintenance, is insanitary, vermin or rat infested, contains filth and contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public.

CE2021-0002

2009 I.P.M.C.

108.1.5 Dangerous structure or premises.

For the purpose of this code, any structure or premises that has any or all of the conditions or defects described below shall be considered dangerous: 1. Any door, aisle, passageway, stairway, exit or other means of egress that does not conform to the approved building or fire code of the jurisdiction as related to the requirements for existing buildings. 2. The walking surface of any aisle, passageway, stairway, exit or other means of egress is so warped, worn loose, torn or otherwise unsafe as to not provide safe and adequate means of egress. 3. Any portion of a building, structure or appurtenance that has been damaged by fire, earthquake, wind, flood, deterioration, neglect, abandonment, vandalism or by any other cause to such an extent that it is likely to partially or completely collapse, or to become detached or dislodged. 4. Any portion of a building, or any member, appurtenance or ornamentation on the exterior thereof that is not of sufficient strength or stability, or is not so anchored, attached or fastened in place so as to be capable of resisting natural or artificial loads of one and one-half the original designed value. 5. The building or structure, or part of the building or structure, because of dilapidation, deterioration, decay, faulty construction, the removal or movement of some portion of the ground necessary for the support, or for any other reason, is likely to partially or completely collapse, or some portion of the foundation or underpinning of the building or structure is likely to fail or give way. 6. The building or structure, or any portion thereof, is clearly unsafe for its use and occupancy. 7. The building or structure is neglected,

damaged, dilapidated, unsecured or abandoned so as to become an attractive nuisance to children who might play in the building or structure to their danger. becomes a harbor for vagrants, criminals or immoral persons, or enables persons to resort to the building or structure for committing a nuisance or an unlawful act. 8. Any building or structure has been constructed, exists or is maintained in violation of any specific requirement or prohibition applicable to such building or structure provided by the approved building or fire code of the jurisdiction, or of any law or ordinance to such an extent as to present either a substantial risk of fire, building collapse or any other threat to life and safety 9. A building or structure, used or intended to be used for dwelling purposes, because of inadequate maintenance, dilapidation, decay, damage, faulty construction or arrangement, inadequate light, ventilation, mechanical or plumbing system, or otherwise, is determined by the code official to be unsanitary. unfit for human habitation or in such a condition that is likely to cause sickness or disease. 10. Any building or structure, because of a lack of sufficient or proper fire-resistance-rated construction, fire protection systems, electrical system, fuel connections, mechanical system, plumbing system or other cause, so determined by the code official to be a threat to life or health. 11 Any portion of a building remains on a site after the demolition or destruction of the building or structure or whenever any building or structure is abandoned so as to constitute such building or portion thereof as an attractive nuisance or hazard to the public.

CE2021-0002

2009 I.P.M.C.

304.7 Roofs and drainage.

The roof and flashing shall be sound, tight and not have defects that admit rain. Roof drainage shall be adequate to prevent dampness or deterioration in the walls or interior portion of the structure. Roof drains, gutters and downspouts shall be maintained in good repair and free from obstructions. Roof water shall not be discharged in a manner that creates a public nuisance.

CE2021-0002

2009 I.P.M.C.

305 INTERIOR STRUCTURE

CE2021-0002

2009 I.P.M.C.

305.1.1 Unsafe conditions.

The following conditions shall be determined as unsafe and shall be repaired or replaced to comply with the International Building Code or the International Existing Building Code as required for existing buildings:

- 1 The nominal strength of any structural member is exceeded by nominal loads, the load effects or the required strength;
2. The anchorage of the floor or roof to walls or columns, and of walls and columns to foundations is not capable of resisting all nominal loads or load effects,
3. Structures or components thereof that have reached their limit state;
4. Structural members are incapable of supporting nominal loads and load effects;
5. Stairs, landings, balconies and all similar walking surfaces, including guards and handrails, are not structurally sound, not properly anchored or are anchored with connections not capable of supporting all nominal loads and resisting all load effects;
6. Foundation systems that are not firmly supported by footings are not plumb and free from open cracks and breaks, are not properly anchored or are not capable of supporting all nominal loads and resisting all load effects.

Exceptions:

- 1 When substantiated otherwise by an approved method.
2. Demolition of unsafe conditions shall be permitted when approved by the code official.

CE2021-0002

2009 I.P.M.C.

305.2 Structural members.

All structural members shall be maintained structurally sound, and be capable of supporting the imposed loads.

Does this property have Homestead Exemption? Yes No

Was there any response from the property owner? Yes No

Are there any photographs? Yes No Who took them? Kevin Vann

Are the photos a true and accurate reflection of the property on the dates taken? Yes No

Date(s) Taken 4/16/2021

When was the last time you visited the property? 1/8/2021

Is property in compliance now? Yes No

What is staff's recommendation?

Witness has chance to ask questions of Inspector or state anything they want into record.

STATEMENT OF CODE CASE COSTS

Date: April 19, 2021

Case: CE2021-0002

Name: FLINCHUM, BEVERLY R

<u>Item</u>	<u>Amount</u>
STAFF COSTS*	
ADMINISTRATIVE COSTS	100.00
POSTAGE COST	
CNV LETTER	0.50
NOV LETTER	6.10
RFH LETTER	6.10
RFH Inspection 04/16/2021 KV	50.00
NOV Inspection 03/12/2021 KV	50.00
CNV Inspection 01/27/2021 KV	50.00
Inspection 01/11/2021 KV	50.00
Initial Inspection 01/08/2021 KV	50.00
Total Costs	362.70

*STAFF COSTS: These actual costs represent the amount owed to Sumter County during the course of this code case. Please remit within the time frame ordered by the Special Master. Make checks payable to: Sumter County Board of County Commissioners. Failure to remit funds in the allotted time frame may result in a lien being filed on any real or personal property and/or foreclosure on any real or personal property owned by the respondent(s).

Sumter County Property Appraiser

updated: 4/15/2021

PARCEL ID: R14B024

<< Next Lower Parcel | Next Higher Parcel >>

2020 Certified Values


Parcel List Generator | Retrieve Tax Record | Show Bldg Sketch
 2020 TRIM (pdf) | GIS Map | Print

Result: 1 of 1

Owner & Property Info

Owner's Name	FLINCHUM BEVERLY R		
Site Address	4817 CR 686, WEBSTER, FL 33597		
Mail Address	12483 SW 50TH WAY, WEBSTER, FL 33597		
Use Desc. (code)	SINGLE FAMILY (00100)		
Sec/Twp/Rng	14/22/21	Neighborhood	9410
Year Built	1966	Tax District	County (1001)
Heated Area	400 (SF)	Market Area	1
Description	NOTE: This description is not to be used as the Legal Description for this parcel in any legal transaction.		
LOT 4 BLK C CROOMACOOCHEE EST PB 3 PG 22			

GIS Aerial



Property & Assessment Values

Land Value	\$4,690.00
Market Value	\$13,190.00
Assessed Value	\$11,410.00
Total Taxable Value	\$11,410.00
Exemptions	None \$0.00

Sales History

Show Similar Sales in 1/2 mile radius

Sale Date	OR Book/Page	OR Inst.Type	Sale V/I (Qual)	Sale Price	Grantee
11/2006	1688/229	WD	I (Q)	\$15,000.00	FLINCHUM BEVERLY R
01/2003	1128/024	DC	I (U)	\$0.00	JONES LYNN
04/1973	140/040		V (Q)	\$5,900.00	JONES K F & LYNN
10/1967	88/657		I (Q)	\$1,900.00	JONES K F & LYNN

Building Characteristics

#	Bldg Style	Bldg Use (code)	Wall Type	Eff Year Built	Area Breakdown
Show Sketch	Single Family	RES 250 (R25)	Wall Type 3	1966	BAS=400 SF
Note: All S.F. calculations are based on exterior building dimensions.					

Land Breakdown

#	Land Use	Land Units	Frontage	Depth
1	Croomacoochee (9008R)	106.00 Front Feet	106.00	110.00

Misc Features

#	Description (code)	Units (dims)	Eff. Year
	NONE		

Sumter County Property Appraiser - Roll Year: 2020

updated: 4/15/2021

Result: 1 of 1

DISCLAIMER

This information was derived from data which was compiled by the Sumter County Property Appraiser Office solely for the governmental purpose of property assessment. This information should not be relied upon by anyone as a determination of the ownership of property or market value. No warranties, expressed or implied, are provided for the accuracy of the data herein, it's use, or it's interpretation. Although regularly updated, this information may not reflect the data currently on file in our office.

Notice:

Under Florida Law, e-mail addresses are public record. If you do not want your e-mail address released in response to a public-records request, do not send electronic mail to this entity. Instead contact this office by phone or in writing.